Wednesday, 6/28/2006 4:19:13 PM Kim Johnston User: **Process Sheet** : SHORT STEP INSTALLATION KIT Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** Job Number : 27760 : 10542 **Estimate Number** AIN. : K591113 P.O. Number Part Number S.O. No. : NIA : D350-591 REV F PG17 : 6/28/2006 **Drawing Number** This Issue : N/A : NC Prsht Rev. Project Number : NIA : SMALL /MED FAB Type **Drawing Revision** First Issue : 27308 **Previous Run** Material : 8/20/2006 Each **Due Date** Qty: 12 Um: Written By Checked & Approved By 04.11.09 KJ/JLM Comment : Est: Reformat **Additional Product** Job Number: Description: Seq. #: **Machine Or Operation:** 1.0 D2171 Clamp Comment: Qty.: 2.0000 Each(s)/Unit Total: 24.0000 Each(s) Clamp Pick: Qty Part Number Description D2171 Clamp D2182B 2.0 Comment: Qty.: 6.9996 f(s) 0.5833 f(s)/Unit Total: Neoprene Cushion-.750 bl Pick: Description Batch Qty Part Number 24870 ~ 7"(2 x 3.5") D2182B Cushion 3.0 D2274 48.0000 Each(s) Comment: Qty.: 4.0000 Each(s)/Unit Total: Radius Block Pick: Description Batch Qty Part Number Radius Block 4 D2274 D23623 4.0 Step Support Bracket Comment: Qty.: 1.0000 Each(s)/Unit Total: 12.0000 Each(s) Step Support Bracket Pick: Qty Part Number Description Batch D2362-3 Support Bracket

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector				
NCR:		WORK ORDER NON-CONF	ORMANCE (NCI	₹)							

NCR:		W	WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B	i	Verification	A	Approval					
DATE	STEP	Section A			Sign & Section C		Approval Design Mgr	Approval QC Inspector					
	-												
					; ; 								
					1								
		· .					·						

Part No:	PAR #:	Fault Category:	NCR:	Yes No	DQA:	Date:
NOTE: Date & initial all entries				QA: N/C	Closed:	Date:

Wednesday, 6/28/2006 4:19:13 PM Date: Kim Johnston User: **Process Sheet** Drawing Name: SHORT STEP INSTALLATION KIT Customer: CU-DAR001 Dart Helicopters Services Job Number: 27760 Part Number: K591113 Job Number: **Machine Or Operation:** Description: Seq. #: D2856400 Abrasion Strip 5.0 Comment: Qty.: Total: 7.2000 f(s)0.6000 f(s)/Unit D2856-600 Pulled to Abrasion Strip Pick: -400 Abd8108 B 25656 Part Number Qty Description 7.2" Abrasion Strip D2856-400-AN337A 6.0 2.0000 Each(s)/Unit Total: 24.0000 Each(s) Comment: Qty.: Bolt Pick: Description Qtv Part Number Batch AN3-37A Bolt 2 AN420A 7.0 Comment: Qty.: 4.0000 Each(s)/Unit Total: 48.0000 Each(s) Bolt Pick: Description Qty Part Number M14855V 4 AN4-20A Bolt AN422A 8.0 Comment: Qty.: 1.0000 Each(s)/Unit Total: 12.0000 Each(s) Bolt Pick: Qty Part Number Description Batch M 18822 AN4-22A Bolt AN960JD10 9.0 4.0000 Each(s)/Unit Total: 48.0000 Each(s) Comment: Qty.: Washer Pick: Batch Qty Part Number Description m 100743 / AN960JD10 Washer 4

Dart Aerospace Ltd

W/O:		WORK ORDER CH	WORK ORDER CHANGES											
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector							
			1 1 1											

NCR:		W	WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC	<u></u>	Corrective Action Section B		Verification Section C	Approval Design Mgr				
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date			Approval QC Inspector			
	-				1 - 1 1						
,	,										
				1							
				1							
							l				
				,							

Part No:	PAR #:	Fault Category: NC	CR:	Yes No DQA:	Date: 06/08) 2=
NOTE: Date & initial all entries				QA: N/C Closed:	Date:

Wednesday, 6/28/2006 4:19:14 PM User: Kim Johnston **Process Sheet** Drawing Name: SHORT STEP INSTALLATION KIT Customer: CU-DAR001 Dart Helicopters Services Job Number: 27760 Part Number: K591113 Job Number: Seq. #: Description: **Machine Or Operation:** Washer AN960JD416 10.0 6.0000 Each(s)/Unit Total: 72.0000 Each(s) Comment: Qty.: Washer Pick: Qty Part Number Description m 1013692 AN960JD416 Washer 6 MS21042L3 11.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 24.0000 Each(s) Nut Pick: Description Qty Batch Part Number m 100 39= MS21042L3 2 Nut 12.0 MS21042L4 Comment: Qty.: 5.0000 Each(s)/Unit Total: 60.0000 Each(s) Nut Pick: Description Qty Part Number 5 MS21042L4 INSPECT 100% KITS FOR COMPLETENESS 13.0 QC4 Comment: INSPECT KITS 100% FOR COMPLETENESS PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location:_ DC 15.0 Comment: DOCUMENT CONTROL HOL.08.22 Inspection Level 21 CL06/08122 Job Completion

Form: rprocess

Page 3

Dart A	erospa	ce Ltd							
W/O:			WO	RK ORDER CHANGES					
DATE	STEP	PRO	OCEDURE CHAI	IGE	Ву	Date	Qty	Approval Mfg / Design Mgr	Approval QC Inspector
	,								
					1				
			·						
			4						
NCR:			WORK ORDE	ER NON-CONFORMANC	E (NCR)			
		Description of NC		Corrective Action Section B		Verifie	cation	Approval	Approval
DATE	STEP	Section A	Initial Design Mgr	Action Description Design Mgr	Sign & Date	í	on C	Design Mgr	QC Inspector
li .									
				.					

				ļ					

NOTE: Date & initial all en	tries		QA: N/C Closed:	Date:
Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
				· ·

5. PARTS LIST

Qty -111A	Qty -113	Qty -115	Qty -117A	Qty -119	Qty -133	Part Number	Description
X						D350-591-111A	Heli-Access-Step ™, Long Step – High Skid
	X					D350-591-113	Heli-Access-Step ™, Short Step – High Skid
		Х		i		D350-591-115	Heli-Access-Step ™, Short Step – Low Skid
			X		1	D350-591-117A	Heli-Access-Step ™, Pre-Flight Step
				х		D350-591-119	Heli-Access-Step ™, Long Step – Low Skid
					X	D350-591-133	Heli-Access-Step ™, Aft Maintenance Step
						D0040	STEP ASSEMBLY (HIGH-SHORT)
	1					D2310	
1						D2311	STEP ASSEMBLY (HIGH-LONG)
		11				D2354	STEP ASSEMBLY (LOW-SHORT)
				1	<u></u>	D2355	STEP ASSEMBLY (LOW-LONG)
					1	D2946-041	STEP ASSEMBLY (MAINTENANCE)
4	2	2	2	2		D2171	CLAMP
4	2	2	2	2		D2182B035	CUSHION
					4	D2230-1	MOUNTING LUG
					4	D2230-3	MOUNTING LUG
8	4	4	4	4		D2274	RADIUS BLOCK
	·	<u> </u>	1			D2362-041	SUPPORT BRACKET
2	1			1		D2362-3	SUPPORT BRACKET
		1				D2362-5	SUPPORT BRACKET
2	1	1	1	1	2	D2856-400-720	ABRASION STRIP
					1	D2945	MOUNTING PLATE
2	2	2		2		AN3-37A	BOLT
			 		2	AN4-7A	BOLT
			<u> </u>		4	AN4-11A	BOLT
			 		8	AN4-14A	BOLT
8	4	4	4	4		AN4-20A	BOLT
1	1	1	 	1	·	AN4-22A	BOLT
4	4	4		4		AN960JD10	WASHER
10	6	6	4	6	14	AN960JD416	WASHER
2	2	2		2		MS21042L3	NUT
9	5	5	4	5	14	MS21042L4	NUT

Qty -121	Qty -122	Qty -123	Qty -124	Part Number	Description
X	122	120_		D350-591-121	Heli-Access-Step ™, Short Step - High Skid, LH
	х			D350-591-122	Heli-Access-Step ™, Short Step - High Skid, RH
		Х		D350-591-123	Heli-Access-Step ™, Short Step – Low Skid, LH
			Х	D350-591-124	Heli-Access-Step ™, Short Step – Low Skid, RH
1				D2351-041	STEP ASSEMBLY (HIGH-SHORT, LH)
	1			D2351-042	STEP ASSEMBLY (HIGH-SHORT, RH)
		1		D2356-041	STEP ASSEMBLY (LOW-SHORT, LH)
			1	D2356-042	STEP ASSEMBLY (LOW-SHORT, RH)
1	1	1	1	D2230-1	MOUNTING LUG
1	1	1	1	D2230-3	MOUNTING LUG
1	1	1	111	D2856-400-720	ABRASION STRIP
2	2	2	2	AN3-37A	BOLT
3	3	3	3	AN4-13A	BOLT U
4	4	4	4	AN960JD10	WASHER
6	6	6	6	AN960JD416	WASHER
2	2	2	2	MS21042L3	NUT
3	3	3	3	MS21042L4	NUT

SHOP COPY
RETURN TO
ENGINEERING
CONTROLLED COPY

BJECT TO AMENDMENT WITHOUT NOTICE WORK ORDER NO. 27760

• COPYRIGHT © 1993 BY DART AEROSPACE LTD •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: F

Date: 04.03.02